

## 2008 Elgin Crosswind

Mounted on a 2008 Freightliner Chassis

55,800 Miles

4,510 Hours

Auxiliary Hydraulic System

Left & Right Gutter Broom Drop Down & Tilt

Dump Switch in Cab

Hopper Deluge System

Battery Disconnect Switch

2 Speed Axle

Arrow Board





