

# 2013 TYMCO 435

Mounted on a 2013 Isuzu NQR Chassis

14,600 Miles

650 Hours

Left & Right Gutter Brooms

Variable Speed Gutter Brooms

Right Gutter Broom Tilt

Auxiliary Hydraulic System

Hi/Low Pressure Washdown System

High Output Water System

Abrasion Protection Package

Dump Switch in Cab

Hopper Deluge System

Hopper Drain System

Pickup Head Curtain Lifter

Auxiliary Hand Hose

Light Bar

Front Spray Bar

Reconditioned

Ready to Sweep







